

ICC-ES Evaluation Report

ESR-2328 FBC Supplement

Reissued October 2017

This report is subject to renewal October 2018.

www.icc-es.org | (800) 423-6587 | (562) 699-0543

A Subsidiary of the International Code Council®

DIVISION: 03 00 00—CONCRETE

Section: 03 16 00—Concrete Anchors

DIVISION: 04 00 00—MASONRY

Section: 04 05 19.16—Masonry Anchors

DIVISION: 06 00 00—WOOD, PLASTICS, AND COMPOSITES

Section: 06 05 23—Wood, Plastic, and Composite Fastenings

REPORT HOLDER:

FASTENING SPECIALISTS, INC.
726 CENTRAL FLORIDA PARKWAY
ORLANDO, FLORIDA 32824
(407) 888-9099
www.tiemax.com

EVALUATION SUBJECT:

TIE MAX ANCHOR BOLTS AND CONTINUOUS ROD TIE-DOWN RUN (CRTR)

1.0 REPORT PURPOSE AND SCOPE

Purpose:

The purpose of this evaluation report supplement is to indicate that the Tie Max anchor bolts and continuous rod tie-down runs (CRTRs), recognized in ICC-ES master evaluation report ESR-2328, have also been evaluated for compliance with the codes noted below.

Applicable code editions:

- 2014 *Florida Building Code—Building*
- 2014 *Florida Building Code—Residential*

2.0 CONCLUSIONS

The Tie Max anchor bolts and CRTRs, described in Sections 2.0 through 7.0 of the master evaluation report ESR-2328, comply with the *Florida Building Code—Building*, and the *Florida Building Code—Residential*, provided the design and installation are in accordance with the 2012 *International Building Code*® (IBC) provisions noted in the master report.

Use of the Tie Max anchor bolts and CRTRs for compliance with the High-Velocity Hurricane Zone provisions of the *Florida Building Code—Building*, and the *Florida Building Code—Residential*, has not been evaluated, and is outside the scope of this supplemental report.

For products falling under Florida Rule 9N-3, verification that the report holder's quality assurance program is audited by a quality assurance entity approved by the Florida Building Commission for the type of inspections being conducted is the responsibility of an approved validation entity (or the code official when the report holder does not possess an approval by the Commission).

This supplement expires concurrently with the master report, reissued October 2017.